

*****ASAP Alert*****

We have received numerous reports of PDC route changes at MIA in a non-standard format with no change marks.

Be aware of this situation at MIA and double check your filed and programmed FMS route prior to pushback.