

*****ASAP ALERT*****

Recently, flights departing KSEA have not flown the Mountain Six SID properly. On the Mountain Six Departure both NEZUG departing to the north and NICHY departing to the south are mandatory fly over points. Do not early turn either of those waypoints before turning to the assigned heading of 070. This is not a navigable departure and crews should fly the assigned heading in JEPPS until overflying NEZUG or NICHY.